

m/045/030




# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT

Salt Lake District Office  
2370 South 2300 West  
Salt Lake City, Utah 84119

IN REPLY REFER TO:

U70306  
2800  
(UT-024)



MAR 29 1995

Mr. Boyd White  
Akzo Salt, Inc.  
1428 James Palmer Road  
Lakepoint, Utah 84074

DOGM  
MINERALS PROGRAM  
FILE COPY

Re: Akzo Water Pipeline right-of-way

Dear Mr. White

A field examination of March 20, 1995, reveals that the area within your water pipeline right-of-way U-70306 remains disturbed and unseeded. The soil is currently saturated and attempts to compact it would be unsuccessful. In addition, it is probably too late in the season to seed the area.

As soon as the soil is dry enough to adequately support construction equipment without serious rutting, the area needs to be compacted and contoured. The areas where roads lead west to Lone Rock are in need of compaction as well. Seeding may be done in the early fall of 1995, according to the stipulations attached to the grant.

We appreciate your prompt attention regarding your right-of-way, and if you have any questions, please contact Sharon Knowlton at (801) 977-4300.

Sincerely,

*Margaret Wyatt*

Margaret Wyatt  
Pony Express Resource Area Manager

DOGM  
MINERALS PROGRAM  
FILE COPY